

Screenprint/Dow

A WORLD OF PRINTING TECHNOLOGIES

- Membrane Switches
- Conductive Printing
- Graphic Overlays
- Graphic Printing
- Graphic Enhancements
- Backlighting
- Engineering Services
- Quality Assurance

Fraction	Decimal	Millimeter	Fraction	Decimal	Millimeter
1/64	.015625	0.397	33/64	.515625	13.097
1/32	.03125	0.794	17/32	.53125	13.494
3/64	.046875	1.191	35/64	.546875	13.891
1/16	.0625	1.588	9/16	.5625	14.288
5/64	.078125	1.984	37/64	.578125	14.684
3/32	.09375	2.381	19/32	.59375	15.081
7/64	.109375	2.778	39/64	.609375	15.478
1/8	.125	3.175	5/8	.625	15.875
9/64	.140625	3.572	41/64	.640625	16.272
5/32	.15625	3.969	21/32	.65625	16.669
11/64	.171875	4.366	43/64	.671875	17.066
3/16	.1875	4.762	11/16	.6875	17.462
13/64	.203125	5.159	45/64	.703125	17.859
7/32	.21875	5.556	23/32	.71875	18.256
15/64	.234375	5.953	47/64	.734375	18.653
1/4	.25	6.350	3/4	.75	19.050
17/64	.265625	6.747	49/64	.765625	19.447
9/32	.28125	7.144	25/32	.78125	19.844
19/64	.296875	7.541	51/64	.796875	20.241
5/16	.3125	7.938	13/16	.8125	20.638
21/64	.328125	8.334	53/64	.828125	21.034
11/32	.34375	8.731	27/32	.84375	21.431
23/64	.359375	9.128	55/64	.859375	21.828
3/8	.375	9.525	7/8	.875	22.225
25/64	.390625	9.921	57/64	.890625	22.622
13/32	.40625	10.319	29/32	.90625	23.019
27/64	.421875	10.716	59/64	.921875	23.416
7/16	.4375	11.112	15/16	.9375	23.812
29/64	.453125	11.509	61/64	.953125	24.209
15/32	.46875	11.906	31/32	.96875	24.606
31/64	.484375	12.303	63/64	.984375	25.003
1/2	.5	12.700	1	1.	25.400

To convert millimeters into inches multiply by	MM	INCH	MM	INCH
.03937	1	.039	14	.5519
	2	.0790	15	.5906
	3	.1181	16	.6300
	4	.1575	17	.6693
	5	.1969	18	.7087
	6	.2362	19	.7480
	7	.2756	20	.7874
	8	.3150	21	.8268
	9	.3543	22	.8661
	10	.3937	23	.9055
	11	.4331	24	.9449
	12	.4724	25	.9843
	13	.5119		